DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/08/2013 FORM APPROVED OMB NO. 0938-0391

TAG REGULATORY OR LSC IDENTIFYING INFORMATION) (K 000) INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/04/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/07/13 Facility Number: 000551 Provider Number: 155381 AIM Number: 100267400 Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Harbour Manor Health & Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in resident	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
NAME OF PROVIDER OR SUPPLIER HARBOUR MANOR HEALTH & LIVING COMMUNITY SUMMARY STATEMENT OF DEFICIENCIES (K4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY WIST SEE PROCESSED BY PILL REGULATORY OR LSC IDENTIFYING INFORMATION) [K 000] INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 2024/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/07/13 Facility Number: 000551 Provider Number: 155381 AlM Number: 100267400 Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Harbour Manor Health & Living Community was from a time 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridor. The facility has a fire facility has a battery operated some detectors in resident			155381	155381 B. WING				
PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) [K 000] INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/04/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/07/13 Facility Number: 000551 Provider Number: 1055381 Alf Number: 100267400 Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Harbour Manor Health & Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (1111) construction and was fully sprinklered. The Tacility has a fire alarm system with smoke detector in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in resident	NAME OF PROVIDER OR SUPPLIER					1667 SHERIDAN RD	, 50,	0172010
A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/04/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/07/13 Facility Number: 000551 Provider Number: 155381 AIM Number: 100267400 Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Harbour Manor Health & Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in resident	PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREF	PREFIX (EACH CORRECTIVE ACTION SHOUL TAG CROSS-REFERENCED TO THE APPRO		BE COMPLETION	
Code Recertification and State Licensure Survey conducted on 02/04/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/07/13 Facility Number: 000551 Provider Number: 155381 AIM Number: 100267400 Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Harbour Manor Health & Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in resident	{K 000}	A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/04/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/07/13 Facility Number: 000551 Provider Number: 155381 AIM Number: 100267400 Surveyor: Mark Caraher, Life Safety Code Specialist At this PSR survey, Harbour Manor Health & Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in resident sleeping rooms. The facility has a capacity of 95 and had a census of 92 at the time of this survey. All areas where residents have customary access were sprinklered. The facility has one detached		{K (000	}		
and had a census of 92 at the time of this survey. All areas where residents have customary access were sprinklered. The facility has one detached								
garage providing facility storage services which was not sprinklered. ABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE	ADODATODY	was not sprinklered.				TTTE		(VC) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/08/2013 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED		
		155381	B. WING			R 03/07/2013	
	/IDER OR SUPPLIER	ING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 1667 SHERIDAN RD NOBLESVILLE, IN 46060				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			IX S	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	SHOULD BE	
C		bert Booher, Life Safety cal Surveyor on 03/07/13.	{K	000)			